

Laucks⁸²_{PLUS}

Testing Laboratories, Inc.

940 South Harney St., Seattle, WA 98108 (206) 767-5060 FAX 767-5063

Certificate

Chemistry, Microbiology and Technical Services

CLIENT: Alaskan Copper Works
P.O. Box 3546
Seattle, WA 98124
ATTN: Raphael

LABORATORY NO. 18989

DATE: Nov. 3, 1989

PO# M11983

REPORT ON: LIQUID

SAMPLE

IDENTIFICATION: Submitted 10/06/89 and identified as shown below:

10-6-3223-M11983 sample from do all saw

TESTS PERFORMED AND RESULTS:

Sample was analyzed for EP Toxicity in accordance with Test Methods for Evaluating Solid Waste, (SW 846), U.S.E.P.A., November, 1986. Extraction was performed using Method 1310. Mercury was determined using Method 7470; other metals performed by ICAP, Method 6010.

parts per million (mg/L)

	<u>Sample</u>	<u>MCL</u>
Arsenic	<0.2	5.0
Barium	0.4	100.
Cadmium	0.01	1.0
Chromium	<0.1	5.0
Lead	15.	5.0
Mercury	<0.005	0.2
Selenium	<0.2	1.0
Silver	<0.1	5.0
Copper	3.2	100.
Nickel	0.2	-
Zinc	0.7	500.



This report is submitted for the exclusive use of the person, partnership, or corporation to whom it is addressed. Subsequent use of the name of this company or any member of its staff in connection with the advertising or sale of any product or process will be granted only on contract. This company accepts no responsibility except for the due performance of inspection and/or analysis in good faith and according to the rules of the trade and of science.

AKC-0015128

Laucks®

Testing Laboratories, Inc.

940 South Harney St., Seattle, WA 98108 (206) 767-5060 FAX 767-5063

Certificate

Chemistry, Microbiology, and Technical Services

Alaskan Copper Works

PAGE NO. 2

LABORATORY NO. 18989

Key

< indicates "less than"

MCL = Maximum Contamination Level allowed per current EPA and State of Washington regulations.

Respectfully submitted,

Laucks Testing Laboratories, Inc.

P. 
B. Gleason

BG:1am



This report is submitted for the exclusive use of the person, partnership, or corporation to whom it is addressed. Subsequent use of the name of this company or any member of its staff in connection with the advertising or sale of any product or process will be granted only on contract. This company accepts no responsibility except for the due performance of inspection and/or analysis in good faith and according to the rules of the trade and of science.

AKC-0015129

Laucks ⁸²_{years}

Testing Laboratories, Inc.

940 South Harney St., Seattle, WA 98108 (206) 767-5060 FAX 767-5063

Certificate

Chemistry, Microbiology and Technical Services

PAGE NO. 2

Alaskan Copper Works

LABORATORY NO. 18989


Key

< indicates "less than"

MCL = Maximum Contamination Level allowed per current EPA and State of Washington regulations.

Respectfully submitted,

Laucks Testing Laboratories, Inc.


B. Gleason

BG:lam



This report is submitted for the exclusive use of the person, partnership, or corporation to whom it is addressed. Subsequent use of the name of this company or any member of its staff in connection with the advertising or sale of any product or process will be granted only on contract. This company accepts no responsibility except for the due performance of inspection and/or analysis in good faith and according to the rules of the trade and of science.

AKC-0015130

Laucks ⁸² years

Testing Laboratories, Inc.

940 South Harney St., Seattle, WA 98108 (206) 767-5060 FAX 767-5063



Certificate

Chemistry, Microbiology, and Technical Services

CLIENT: Alaskan Copper Works
P.O. Box 3546
Seattle, WA 98124
ATTN: Raphael

LABORATORY NO. 18989

DATE: Nov. 3, 1989

PO# M11983

REPORT ON: LIQUID

SAMPLE

IDENTIFICATION: Submitted 10/06/89 and identified as shown below:

10-6-3223-M11983 sample from do all saw

TESTS PERFORMED AND RESULTS:

Sample was analyzed for EP Toxicity in accordance with Test Methods for Evaluating Solid Waste, (SW 846), U.S.E.P.A., November, 1986. Extraction was performed using Method 1310. Mercury was determined using Method 7470; other metals performed by ICAP, Method 6010.

parts per million (mg/L)

	<u>Sample</u>	<u>MCL</u>
Arsenic	<0.2	5.0
Barium	0.4	100.
Cadmium	0.01	1.0
Chromium	<0.1	5.0
Lead	15.	5.0
Mercury	<0.005	0.2
Selenium	<0.2	1.0
Silver	<0.1	5.0
Copper	3.2	100.
Nickel	0.2	-
Zinc	0.7	500.



This report is submitted for the exclusive use of the person, partnership, or corporation to whom it is addressed. Subsequent use of the name of this company or any member of its staff in connection with the advertising or sale of any product or process will be granted only on contract. This company accepts no responsibility except for the due performance of inspection and/or analysis in good faith and according to the rules of the trade and of science.

AKC-0015131

Raphael 11/9/89.

Laucks ⁸¹ years

Testing Laboratories, Inc.



Invoice

940 South Harney St., Seattle, Washington 98108 (206) 767-5060 FAX 767-5063

Chemistry, Microbiology, and Technical Services

CLIENT: Alaskan Copper Works
P.O. Box 3546
Seattle, WA 98124
ATTN: Raphael

INVOICE NO. 18989

DATE: Nov. 3, 1989

PO# M11983

Do All SAW
3223
EP-100
Passed

For the analysis of MATERIAL: -----\$238.00

Net 30 Days

The sole liability of these laboratories for these services, including claims for negligence, strict liability in tort or warranty, shall not exceed the amount of this invoice. Samples may be discarded after analysis unless otherwise requested.

Fed. Empl. ID No. 91-0580763



AKC-0015132

Raphael 11/9/89.

Laucks® Testing Laboratories, Inc.

940 South Harney St., Seattle, Washington 98108 (206) 767-5060 FAX 767-5063



Invoice

Chemistry, Microbiology, and Technical Services

CLIENT: Alaskan Copper Works
P.O. Box 3546
Seattle, WA 98124
ATTN: Raphael

INVOICE NO. 18989

DATE: Nov. 3, 1989

PO# M11983

For the analysis of MATERIAL: -----\$238.00

Net 30 Days

The sole liability of these laboratories for these services, including claims for negligence, strict liability in tort or warranty, shall not exceed the amount of this invoice. Samples may be discarded after analysis unless otherwise requested.

Fed. Empl. ID No. 91-0580763



AKC-0015133